

上海博众测量技术有限公司

Bodhi (Shanghai) measurement technology Co.,Ltd.
NO.32,ShuPing Road, JiadingDistrict,ZIP201808,
Shanghai R.P.China
TEL: 0086 21 6630 8161/62/63
FAX: 0086 21 6630 8167

USER'S GUIDE

Vaisala CARBOCAP® Carbon Dioxide Probe GMP231




Table of Contents

CHAPTER 1

GENERAL INFORMATION	7
About This Manual	7
Contents of This Manual	7
Version Information	8
Related Manuals	8
Documentation Conventions	8
Safety	9
ESD Protection	9
Recycling	9
Regulatory Compliances	10
Patent Notice	10
Trademarks	10
Software License	10
Warranty	11

CHAPTER 2

PRODUCT OVERVIEW	12
Introduction to GMP231	12
Basic Features and Options	13
GMP231 Parts	14
Operating Principle of CO₂ Measurement	15
Environmental Compensation	17
Pressure Compensation	17
Temperature Compensation	17
Background Gas Compensations	18
Probe Startup	18
Analog Output Overage Behavior	19

CHAPTER 3

INSTALLATION	20
Thermal Management	20
Avoiding Condensation	21
Probe Installation Depth	21
Dimensions	22
Recommended Installation	23
Wiring	24
Power Supply	24

CHAPTER 4

VAISALA INDUSTRIAL PROTOCOL	25
Overview	25

- Physical Interface25**
- Connecting with a Computer.....26**
 - Installing the Driver for the USB Service Cable26
 - Terminal Application Settings.....27
- Serial Commands28**
- Showing Device Information29**
 - Show Probe Information29
 - Show Serial Number.....30
 - Show Firmware Version30
 - Show Firmware Information30
 - Show Probe Uptime.....30
 - Show Command List31
- Serial Line Output Commands31**
 - Start Measurement Output31
 - Stop Measurement Output32
 - Set Output Interval.....32
 - Output a Reading Once.....32
 - Set Measurement Output Format.....33
 - FORM Command Examples34
- Changing Measurement Settings.....35**
 - Set Compensation Modes35
 - Change Compensation Setpoint Values36
 - Set Measurement to Standby Mode.....37
- Configuring Serial Line Operation38**
 - Set Serial Line Operating Mode38
 - Set Serial Line Settings39
 - Set Probe Address39
 - Set Serial Line Response Time.....40
 - Set Serial Line Echo.....40
- Calibration Commands41**
 - Adjust CO₂ Measurement.....41
 - Set Calibration Date42
 - Set Calibration Info Text.....43
 - Adjust Temperature Measurement.....43
 - Adjust Pressure Measurement44
- Configuring Analog Output45**
 - Set Analog Output Scaling45
 - Set Analog Output Mode45
 - Set Analog Output Clipping and Error Limit46
 - Test Analog Output.....47
- Other Commands.....47**
 - Enable Advanced Commands47
 - Connecting to Probe in POLL Mode.....48
 - Closing the Connection to a Probe in POLL Mode48
 - Show Active Errors48
 - Reset Probe.....49
 - Restore Factory Settings49

CHAPTER 5

- I²C INTERFACE.....50**
- Overview50**
 - Physical Interface50
 - Communication Parameters51
 - Addressing.....51

Communication Flow	52
GMP231 State Machine	53
Examples of Communication Flow	54
Timing	56
Status Byte	56
Checksum	56
Status Word	57
Commands	59
Get_Interface_Version	59
Get_Parameter	60
Example: Read CO ₂ Measurement Result	61
Set_Parameter	62
Example: Set Compensation Temperature	63
Get_Parameter_Info	64
Adjust	65
Adjusting Measurement	66
One Point Adjustment	66
Two Point Adjustment	67
Data Registers	67
Data Formats	67
Register Table	68

CHAPTER 6

MAINTENANCE	71
Cleaning	71
Chemical Tolerance	71
Changing the Filter	72
Changing the Silicone Plug	73
Calibration and Adjustment	74
Calibration Setup	74
Using Ambient Air as Reference	75
Using a Calibration Gas as Reference	75
Effect of Environmental Compensations	75
Limits of Adjustment	76
Adjustment Types	76
I ² C Interface	77
Vaisala Industrial Protocol	77
MI70 Hand-Held Indicator	77

CHAPTER 7

OPERATING WITH MI70 INDICATOR	78
Overview of MI70 Support	78
Connecting GMP231 to MI70 Indicator	78
Changing Environmental Compensation Settings with MI70 Indicator	79
Calibration and Adjustment with MI70 Indicator	80
1-Point Adjustment with an MI70-Compatible Reference Probe	80
1-Point Adjustment with a Reference Gas	82

CHAPTER 8

TROUBLESHOOTING	84
Problem Situations	84

Analog Output Error State	85
Technical Support	85
Product Returns.....	85

CHAPTER 9

TECHNICAL DATA	86
Specifications	86
Spare Parts and Accessories	88

List of Figures

Figure 1	GMP231 Installed Through a Chamber Wall (Example).....	12
Figure 2	GMP231 Parts.....	14
Figure 3	CARBOCAP® Sensor of the GMP231.....	15
Figure 4	CO ₂ Measurement Inside the Incubator.....	16
Figure 5	Probe Installation Depth.....	21
Figure 6	Probe Dimensions without Silicone Plug.....	22
Figure 7	Probe Dimensions with Silicone Plug.....	22
Figure 8	Electronics Housing Dimensions.....	22
Figure 9	Attachment Bracket Dimensions.....	22
Figure 10	Recommended Installation.....	23
Figure 11	PuTTY Terminal Application.....	27
Figure 12	Hardware Schematic.....	50
Figure 13	GMP231 State Machine.....	54
Figure 14	Get_Parameter with ACK.....	54
Figure 15	Set_Parameter with ACK.....	55
Figure 16	Get_Parameter with NACK.....	55
Figure 17	Get_Parameter with Alarm.....	55
Figure 18	Changing the Filter.....	72
Figure 19	Changing the Silicone Plug.....	73
Figure 20	Inserting the Calibration Adapter over the Filter.....	74
Figure 21	CO ₂ Reading on MI70 Screen.....	78
Figure 22	CO ₂ Reading with Tcomp and Pcomp on MI70 Screen.....	79
Figure 23	GMP231 Compensation Settings on MI70 Screen.....	79
Figure 24	Functions Menu.....	80
Figure 25	Comparing Readings in MI70 Adjustment Mode.....	81
Figure 26	Selecting the Adjustment Mode.....	81
Figure 27	Functions Menu.....	82
Figure 28	MI70 Adjustment Mode.....	82
Figure 29	Selecting the Adjustment Mode.....	83
Figure 30	Entering the Reference CO ₂ Concentration.....	83

List of Tables

Table 1	Manual Revisions	8
Table 2	Related Manuals	8
Table 3	Applicable Patents	10
Table 4	GMP231 Connector Pinout	24
Table 5	Cable DRW240977	24
Table 6	Default Serial Interface Settings	25
Table 7	Basic Serial Commands	28
Table 8	Advanced Serial Commands	29
Table 9	FORM Command Parameters	33
Table 10	FORM Command Modifiers	33
Table 11	Selection of Output Modes	38
Table 12	GMP231 I ² C Address	51
Table 13	GMP231 Device Address	51
Table 14	Invoke Message in GMP231 I ² C Interface	52
Table 15	Response Message in GMP231 I ² C Interface	53
Table 16	Timing	56
Table 17	Status Byte	56
Table 18	Status Word Content	58
Table 19	Get_Interface_Version Invoke Message	59
Table 20	Get_Interface_Version Response Message	59
Table 21	Get_Parameter Invoke Message	60
Table 22	Get_Parameter Response Message	60
Table 23	Get_Parameter Invoke Message Example	61
Table 24	Get_Parameter Response Message Example	61
Table 25	Set_Parameter Invoke Message	62
Table 26	Set_Parameter Response Message	62
Table 27	Set_Parameter Return Codes	62
Table 28	Example Set_Parameter Invoke Message	63
Table 29	Example Set_Parameter Response Message	63
Table 30	Get_Parameter_Info Invoke Message	64
Table 31	Get_Parameter_Info Response Message	64
Table 32	Parameter Data Types	64
Table 33	Parameter Persistence	64
Table 34	Adjust Invoke Message	65
Table 35	Adjust Response Message	65
Table 36	Adjustment Subcommands	65
Table 37	Adjustment Parameters	65
Table 38	Adjustment Return Codes	66
Table 39	Data Formats	67
Table 40	GMP231 Register Table	68
Table 41	Possible Problem Situations and Their Remedies	84
Table 42	Performance	86
Table 43	Operating Environment	87
Table 44	Inputs and Outputs	87
Table 45	Mechanics	87
Table 46	Spare Parts and Accessories for GMP231	88

CHAPTER 1

GENERAL INFORMATION

This chapter provides general notes for the manual and the GMP231 probe.

About This Manual

This manual provides information for installing, operating, and maintaining the Vaisala CARBOCAP[®] Carbon Dioxide Probe GMP231.

Contents of This Manual

This manual consists of the following chapters:

- Chapter 1, General Information, provides general notes for the manual and the GMP231 probe.
- Chapter 2, Product Overview, introduces the GMP231 probe and its features.
- Chapter 3, Installation, provides you with information that is intended to help you install the GMP231.
- Chapter 4, Vaisala Industrial Protocol, describes the Vaisala Industrial Protocol implementation of the GMP231.
- Chapter 5, I2C Interface, describes the I2C interface implementation of the GMP231.
- Chapter 6, Maintenance, provides information that is needed in the basic maintenance of the GMP231.
- Chapter 8, Troubleshooting, describes possible problems, their probable causes and remedies, and provides contact information for technical support.
- Chapter 9, Technical Data, provides the technical data of the GMP231.

Version Information

Table 1 Manual Revisions

Manual Code	Description
M211501EN-D	December 2014. This manual. Applicable from software version 1.1.0 onward. Updated section Status Word on page 57.
M211501EN-C	May 2014. Previous version. Updated description for ENV command in section Change Compensation Setpoint Values on page 36.
M211501EN-B	March 2014. Applicable from software version 1.1.0 onward. Added instructions for operation with the MI70 hand-held indicator. Updated description of I ² C interface and Vaisala Industrial Protocol. Updated description of environmental compensations. Updated instructions for calibration and adjustment. Updated technical specification.
M211501EN-A	September 2013. First version.

Related Manuals

Table 2 Related Manuals

Manual Code	Manual Name
M211603EN	GMP231 Quick Guide

Documentation Conventions

Throughout the manual, important safety considerations are highlighted as follows:

WARNING Warning alerts you to a serious hazard. If you do not read and follow instructions very carefully at this point, there is a risk of injury or even death.

CAUTION Caution warns you of a potential hazard. If you do not read and follow instructions carefully at this point, the product could be damaged or important data could be lost.

NOTE Note highlights important information on using the product.

Safety

The GMP231 probe delivered to you has been tested for safety and approved as shipped from the factory. Note the following precautions:

WARNING

When returning a product for calibration or repair, make sure it has not been exposed to dangerous contamination, and is safe to handle without special precautions.

CAUTION

Do not modify the unit. Improper modification can damage the product or lead to malfunction.

CAUTION

Do not open the probe housing. There are no user serviceable parts inside.

ESD Protection

Electrostatic Discharge (ESD) can cause immediate or latent damage to electronic circuits. Vaisala products are adequately protected against ESD for their intended use. It is possible to damage the product, however, by delivering an electrostatic discharge when touching an exposed contact on the product.

To make sure you are not delivering high static voltages yourself, avoid touching the pins on the M12 connector.

Recycling



Recycle all applicable material.



Dispose of the unit according to statutory regulations. Do not dispose of with regular household refuse.

Regulatory Compliances

GMP231 is in conformity with the provisions of the following EU directives:

- EMC-Directive
- RoHS-Directive

Conformity is shown by compliance with the following standards:

- EN 61326-1: Electrical equipment for measurement, control, and laboratory use – EMC requirements – Generic environment.
- EN 550022: Information technology equipment – Radio disturbance characteristics – Limits and methods of measurement.



Patent Notice

GMP231 is protected by the following patents and their corresponding national rights:

Table 3 Applicable Patents

Patent Issued By	Patent Number
United States Patent and Trademark Office	US 5,827,438
	US 6,177,673
European Patent Office	EP0776023
	EP0922972
German Patent and Trade Mark Office	69615635
Japan Patent Office	4263285
Finnish Patent Office	112005
	105598

Trademarks

CARBOCAP[®] is a registered trademark of Vaisala Oyj.

All other trademarks are the property of their respective owners.

Software License

This product contains software developed by Vaisala. Use of the software is governed by license terms and conditions included in the applicable supply contract or, in the absence of separate license terms and conditions, by the General License Conditions of Vaisala Group.

Warranty

Please observe that any such warranty may not be valid in case of damage due to normal wear and tear, exceptional operating conditions, negligent handling or installation, or unauthorized modifications. Please see the applicable supply contract or Conditions of Sale for details of the warranty for each product.

CHAPTER 2

PRODUCT OVERVIEW


This chapter introduces the GMP231 probe and its features.

Introduction to GMP231

The Vaisala CARBOCAP® Carbon Dioxide Probe GMP231 is designed for incubator manufacturers requiring accurate and reliable carbon dioxide measurements and sterilization durability at high temperatures.

The GMP231 probe is based on Vaisala's patented CARBOCAP® technology and a new type of infra-red light source. The probe can remain in place during high-temperature sterilization cycles that heat the chamber interior to 180 °C. Special design of the probe enables easy installation through the incubator wall and ensures that the sensor optics and electronics are separated and thermally insulated.

Sensor performance is optimized at 5 %CO₂ measurement. GMP231 also has an internal pressure sensor, which allows compensation of the measurement according to ambient pressure. Since dust and most chemicals do not affect the measurement, and the effect of water vapor can be compensated for, GMP231 is accurate and stable at CO₂ incubator conditions.




1403-144

Figure 1 GMP231 Installed Through a Chamber Wall (Example)

Basic Features and Options

- CO₂ measurement range 0 ... 20 %CO₂.
- Temperature durability in standby mode up to 195 °C (383 °F). See section Thermal Management on page 20.
- Vaisala CARBOCAP[®] CO₂ sensor with excellent long-term stability. See sections Operating Principle of CO₂ Measurement on page 15 and Specifications on page 86.
- Measurement compensated for effects of pressure, temperature, and background gas. Pressure compensation based on integrated pressure sensor. See section Environmental Compensation on page 17.
- Heating to avoid condensation on optical elements.
- Analog output: one current output channel (0 ... 20 mA or 4 ... 20 mA).
- Digital output:
 - I²C.
 - RS-485 (non-isolated) with Vaisala Industrial Protocol.

GMP231 Parts



1403-153

Figure 2 GMP231 Parts

- 1 = Electronics housing. Contains the main component board, including the digital pressure sensor.
- 2 = Holes for M4 screws on both sides of the housing. Maximum screw depth 8 mm. Two screws included, type BN 10649 M4.
- 3 = Type label on housing cover (not shown).
- 4 = 8-pin M12 connector. For pinout, see Table 4 on page 24.
- 5 = Probe body.
- 6 = Measurement cuvette with optics and CARBOCAP[®] CO₂ sensor.
- 7 = PTFE filter.
- 8 = Silicone plug for sealing the lead-through.
Recommended accessory, suitable for \varnothing 44 mm lead-throughs.

CAUTION

Do not open the electronics housing; there are no user serviceable parts inside. All wiring is done through the M12 connector (4).

Operating Principle of CO₂ Measurement

The Vaisala CARBOCAP[®] sensor that is used in the GMP231 is a silicon-based, non-dispersive infrared (NDIR) sensor for the measurement of gaseous carbon dioxide. It is especially designed to tolerate high temperatures in standby mode, up to 195 °C (383 °F). This allows it to be used in applications that utilize high temperature for heat sterilization. The operating temperature range of the sensor is 0 ... +70 °C (+32 ... +158 °F).





Figure 3 CARBOCAP[®] Sensor of the GMP231

The sensitivity to carbon dioxide is based on absorption of infrared light at a characteristic wavelength. The light is emitted by a novel, silicon-based microchip emitter into the cuvette which contains the gas to be measured. After reflection from the mirror, the light intensity is measured with a thermopile chip at a wavelength chosen by a micromechanical Fabry–Pérot interferometer (FPI) and a band pass filter. A hermetically sealed sapphire window is used to protect the sensor chips from moisture and contamination. A heater chip is utilized to prevent condensation in normal operation.

The carbon dioxide measurement consists of two steps: First, the FPI is electrically tuned so that its pass band coincides with the characteristic absorption wavelength of carbon dioxide and the signal is recorded. Second, the pass band is shifted to a wavelength where no absorption occurs in order to get a reference signal. The ratio of these two signals, one at the absorption wavelength and the other at the reference wavelength, gives the fraction of light absorption from which the carbon dioxide concentration is calculated. The reference signal compensates the possible effects of sensor aging and signal attenuation due to dirt on optical surfaces, making the sensor very stable over time.



1403-161

Figure 4 CO₂ Measurement Inside the Incubator

- 1 = Chamber wall.
- 2 = Chamber interior.
- 3 = Light source.
- 4 = Band pass filter.
- 5 = Ambient air (400 ... 1000 ppm CO₂).
- 6 = Light absorbed by CO₂ in the incubator gas.
- 7 = Thermopile detector.
- 8 = Fabry-Perot interferometer.
- 9 = Sapphire window. Separates the sensor's active components from the measured environment.
- 10 = Gold-plated mirror.

Environmental Compensation

GMP231 improves the CO₂ measurement accuracy by applying various environmental compensations. GMP231 compensates for the effects of:

- Pressure
- Temperature
- Background gas oxygen (O₂) content
- Background gas relative humidity (%RH)

Compensation parameters are configured on the order form when ordering the probe, and can later be updated using serial commands, MI70 Indicator, or I²C protocol. If the probe is integrated in a system that measures one or more of the compensation parameters, they can be updated to the probe continuously.

You can also turn off any of the compensations. In that case, GMP231 uses the default compensation value that is mathematically neutral for the probe's internal compensation model.

For the effect of the compensations on measurement accuracy, refer to Table 42 on page 86.

Pressure Compensation

There is a pressure sensor on the component board of the GMP231 that provides a live measurement of ambient pressure. GMP231 can compensate the CO₂ measurement based on this pressure reading, or it can use a fixed setpoint. Using the GMP231's own sensor is recommended for most applications.

If pressure compensation is turned off, GMP231 uses the default compensation value of 1013.2 hPa.

Temperature Compensation

GMP231 can measure the approximate temperature of the CARBOCAP[®] sensor for compensation, or use a fixed setpoint. The temperature measurement is accurate enough to be useful for compensation, and is recommended for use unless a dedicated temperature measurement is available and can be regularly updated to the GMP231.

If temperature compensation is turned off, GMP231 uses the default value of +37 °C (+98.6 °F).

Background Gas Compensations

Compensation for background gas parameters are based on setpoint values only, as GMP231 has no internal measurement for oxygen concentration or humidity. The default setpoint values are as follows:

- Oxygen concentration: 19.7 %O₂.
- Relative humidity: 93 %RH.

If background gas compensations are turned off, GMP231 uses the value 0% for both.

Probe Startup

When powered on, GMP231 starts up within 10 seconds. Measurements from the outputs (digital and analog) become available during this time but note that they will only reach specified accuracy after a one minute warm-up period. For this reason, you should design the incubator's control system so that it does not rely on measurements from GMP231 during this time.

NOTE

Specifically note that the CO₂ reading will rise to the correct reading as the sensor's infrared emitter achieves operation temperature.

Analog Output Overrange Behavior

Analog output of the GMP231 has a defined behavior when the values measured by the probe are outside the scaled analog output range:

- Output is allowed to go 10% over the scaled range.
- Output is set to error state when measured value is more than 10% outside the scaled range. See section Analog Output Error State on page 85.
- Output resumes normal function when measured value returns to within 10% of the selected range.

For example, consider a GMP231 with 0 ... 20 mA analog output, scaled to 0 ... 10 %CO₂.

- When measured CO₂ rises above 10 %CO₂, the output rises above 20 mA.
- The output keeps rising until the measurement is 11 %CO₂, at which point the probe outputs 22 mA.
- If the CO₂ level rises above 11 %CO₂, the output enters the error state, which is 23 mA for the 0 ... 20 mA output.

NOTE

This overrange and error state behavior is specific to the analog output, and does not affect the readings provided by the digital outputs.

You can change the analog output overrange behavior using the **AOVER** command. See section Set Analog Output Clipping and Error Limit on page 46.

CHAPTER 3

INSTALLATION

This chapter provides you with information that is intended to help you install the GMP231.

Thermal Management

GMP231 is designed to remain installed during typical heat sterilization cycles that raise the chamber temperature to 180 °C (356 °F). Since 180 °C is the target temperature for sterilization, it is likely that there will be hotspots inside the chamber that are above this temperature. Avoid installing the GMP231 near such hotspots, for example near heating elements. Do not expose the GMP231 to temperatures higher than 195 °C / 383 °F.

The following considerations are most important for achieving the specified heat durability and measurement stability:

- Only the sensor and its filter should be exposed to heat. The filter must be completely in the heated chamber. The probe body must remain inside the unheated chamber wall so that only the end of the probe body extends exactly 2.5 mm into the chamber.
- During the sterilization cycle, you must set the GMP231 to **standby mode** (turns off the CO₂ measurement), or power off the probe completely. The GMP231 will automatically stop its measurement cycle if it detects a high temperature, but it is best if the incubator's control system set the GMP231 to standby mode when the sterilization cycle is started.
- The installation tube must be sealed from the chamber side to limit heat conduction, and to prevent CO₂ in the chamber from entering the probe. Vaisala recommends a 44 mm diameter installation tube together with Vaisala's silicone plug.
- If the chamber wall contains heating elements, or has a construction where hot air is circulated inside the wall, design the installation tube so that excessive heat is not conducted to the GMP231.

Avoiding Condensation


The sensor head of the GMP231 is heated during normal operation, which prevents condensation from forming inside the filter and on the optical surfaces. The heating is not on when GMP231 is in standby mode or unpowered. For this reason, keep the probe powered and operating when the incubator is in use and humidity inside the chamber is high.

Correct installation depth of the probe is also important for preventing condensation from running to the sensor along the chamber wall. See below.

Probe Installation Depth

GMP231 must be installed so that only the sensor element and the filter are inside the chamber. If the probe is longer the installation tube, the extra length should extend to the outside of the chamber.


The installation depth must be 2.5 mm. This installation depth provides the specified heat durability of the probe, and allows the silicone plug to seal the Ø44 mm installation tube properly.



1403-154


Figure 5 Probe Installation Depth

Dimensions




1403-108

Figure 6 Probe Dimensions without Silicone Plug




1403-110

Figure 7 Probe Dimensions with Silicone Plug



1403-112

Figure 8 Electronics Housing Dimensions



1403-109


Figure 9 Attachment Bracket Dimensions

Recommended Installation

GMP231 is designed to be installed through a chamber wall, and attached to the chamber chassis using an attachment bracket and the two screw holes on the side of the probe. As the installation depth of the probe inside the chamber is critical (see section Probe Installation Depth on page 21), the mounting method must allow the probe to be positioned exactly.

NOTE

The probe and electronics housing must remain outside the heated chamber. The electronics housing should be in a ventilated space that is open to ambient air.



1403-123

Figure 10 Recommended Installation


- 1 = Ambient air.
- 2 = Chamber wall.
- 3 = Chamber interior.
- 4 = GMP231 Electronics housing.
- 5 = M4 screw holes on both sides of the probe housing.
- 6 = 8-pin M12 connector. For pinout, see section Wiring on page 24.
- 7 = Cable.
- 8 = CARBOCAP[®] sensor under PTFE filter. The filter must be inside the chamber completely.
- 9 = Silicone plug. Insert the plug over the probe from inside the chamber.
- 10 = Ø 44 mm installation tube through the chamber wall.
The diameter is important for proper sealing by the silicone plug.

Wiring

GMP231 provides several outputs you can use. Connect the output pins you need, and the power supply and ground pins. Use a shielded cable, and connect the shield to the chassis of the GMP231's M12 connector, and to ground on the other side.


Ground pin 5 to put the probe in standby mode (stops CO₂ measurement). The probe resumes normal measurement operation when pin 5 is no longer grounded, unless its internal measurement shows the temperature is too high.

Table 4 GMP231 Connector Pinout

Male 8-pin M12	Pin #	Function
	1	I ² C SDA
	2	RS-485 D-
	3	I ² C SCL
	4	Analog output +
	5	Standby
	6	RS-485 D+
	7	Power supply +
	8	Ground
	-	Shield

Vaisala's standard connection cable for the GMP231 (order code DRW240977) is a 90 cm long cable with female 8-pin M12 connector on one end, and open ended wires on the other. It supports all outputs from the GMP231, and connects the cable shield to the connector chassis.

Table 5 Cable DRW240977

Female 8-pin M12	Pin #	Function	Wire Color
	1	I ² C SDA	White
	2	RS-485 D-	Brown
	3	I ² C SCL	Green
	4	Analog output +	Yellow
	5	Standby	Gray
	6	RS-485 D+	Pink
	7	Power supply +	Blue
	8	Ground	Red
	-	Shield	Black

Power Supply

The supply voltage range of the GMP231 is 11 ... 30 VDC.
If the analog output is used, the supply voltage range is 20 ... 30 VDC.

The maximum power consumption is 1 W.

CHAPTER 4

VAISALA INDUSTRIAL PROTOCOL

This chapter describes the Vaisala Industrial Protocol implementation of the GMP231.

Overview

RS-485 line of the GMP231 provides an implementation of the Vaisala Industrial Protocol that can be used for service and configuration use, or for interfacing with the incubator's control system. The protocol is a plaintext protocol suitable for use both by human operators and automated systems.

Table 6 Default Serial Interface Settings

Property	Description / Value
Baud rate	19200
Parity	None
Data bits	8
Stop bits	1
Flow control	None

Physical Interface

The physical interface is a non-isolated 3-wire interface. The data lines are RS-485 D- and RS-485 D+. Ground is shared with power supply.

The connector is an 8-pin male M12. For connector pinout and wiring information, see section Wiring on page 24.

Connecting with a Computer

Connecting with a computer allows you to configure and troubleshoot your probe using serial line commands. For a list of commands, see section Serial Commands on page 28.

When connecting using a computer, use the Vaisala USB cable (Vaisala order code 221040) and a suitable terminal application:

- If you have not used the Vaisala USB cable before, install the driver before attempting to use the cable. Refer to section Installing the Driver for the USB Service Cable below for detailed instructions.
- For more information on using a terminal application, see section Terminal Application Settings on page 27.

Installing the Driver for the USB Service Cable

Before taking the USB service cable into use for the first time, you must install the provided USB driver on your computer (requires Windows). When installing the driver, you must accept any security prompts that may appear.

1. Check that the USB service cable is not connected. Disconnect the cable if you have already connected it.
2. Insert the media that came with the cable.
3. Run the USB driver installation program (setup.exe), and accept the installation defaults. The installation of the driver may take several minutes.
4. After the driver has been installed, connect the USB service cable to a USB port on your computer. Windows will detect the new device, and use the driver automatically.
5. The installation has reserved a COM port for the cable. Verify the port number, and the status of the cable, using the **Vaisala USB Instrument Finder** program that has been installed in the Windows Start menu.

Windows will recognize each individual service cable as a different device, and reserve a new COM port. Remember to use the correct port in the settings of your terminal program.

Terminal Application Settings

The steps below describe how to connect to the probe using the PuTTY terminal application for Windows and a USB computer connection cable:

1. Connect the USB serial interface cable between your PC and the M12 connector of the probe.
2. Start the PuTTY application.
3. Select **Connection > Serial & USB** and check that the correct COM port is selected in the **Serial or USB line to connect to** field.


If you are using the PuTTY terminal application supplied by Vaisala, you can press the **USB Finder** button to open the **Vaisala USB Instrument Finder** program.

4. Check that the other serial settings are correct for your connection, and change if necessary. **Flow control** should be set to **None** unless you have a reason to change it.
5. Click the **Open** button to open the connection window and start using the serial line.

NOTE

If PuTTY is unable to open the serial port you selected, it will show you an error message instead. If this happens, restart PuTTY and check the settings.

6. You may need to adjust the **Local echo** setting in the **Terminal** category to see what you are typing on the serial line. To access the configuration screen while a session is running, click the right mouse button over the session window, and select **Change Settings...** from the pop-up menu.



0807-004

Figure 11 PuTTY Terminal Application

Serial Commands

All commands can be issued either in uppercase or lowercase. In the command examples, the keyboard input by the user is in **bold** type.

The notation <cr> refers to pressing the carriage return (**Enter**) key on your computer keyboard. Enter a <cr> to clear the command buffer before starting to enter commands.

Table 7 Basic Serial Commands

Command	Description
?	Show probe information.
CLOSE	Close connection to probe (POLL mode)
ECHO	Show or set remote echo mode.
ENV	Show or set environmental parameters.
ERRS	Show currently active errors.
FORM [modifier string]	Show or set output format.
HELP	Show list of currently available serial commands.
INTV [0 ... 9999 s/min/h]	Set continuous output interval for R command.
OPEN [address]	Open connection to probe in POLL mode
PASS [1300]	Access advanced serial commands.
R	Start the continuous outputting.
RESET	Reset the probe.
S	Stop the continuous outputting.
SDELAY [0 ... 255]	Show or set serial line transmission delay in milliseconds.
SEND	Output measurement message once.
SERI [baud data stop parity]	Show or set the serial interface settings
SMODE [mode]	Show or set startup serial mode: RUN, STOP, or POLL.
SNUM	Show probe serial number.
STANDBY [on/off]	Standby mode on/off (turn off measurement)
SYSTEM	Show probe firmware information
TIME	Show probe operation hours and uptime
VERS	Show probe firmware version.

Table 8 **Advanced Serial Commands**

Command	Description
ADDR [0 ... 254]	Show or set probe address.
AMODE	Show or set analog output mode.
AOVER	Show or set analog output overrange and clipping behavior.
ASEL	Show or set analog output parameter.
ATEST	Test analog output.
CCO2	Adjust CO ₂ measurement gain and offset.
CDATE	Show or set calibration date.
CP	Adjust pressure measurement offset.
CT	Adjust temperature measurement offset.
CTEXT	Show or set calibration information.
FRESTORE	Restore probe to factory settings.
O2CMODE	Show or set oxygen compensation mode.
PCMODE	Show or set pressure compensation mode.
RHCMODE	Show or set humidity compensation mode.
TCMODE	Show or set temperature compensation mode.

Showing Device Information

Show Probe Information

The ? command outputs a listing of probe information.

```
?<cr>
```

Command ?? is a similar command that is designed to be used if the probe is in POLL mode but its address is unknown. The probe will respond to the ?? command even while in POLL mode. Do not use the ?? command if you have more than one probe on an RS-485 line.

Example:

```
?
Device           : GMP231
Copyright        : Copyright (c) Vaisala Oyj 2013. All rights reserved.
SW Name          : GMP231
SW version       : 1.0.1.1537
Snum             : J1320082
Calibrated       : 2014-03-11
Address          : 1
Smode           : STOP
```

Show Serial Number

SNUM<cr>

Example:

```
snm  
Serial number      : J1320082
```

Show Firmware Version

VERS<cr>

Example:

```
vers  
GMP231 / 1.1.0.1537
```

Show Firmware Information

SYSTEM<cr>

Example:

```
system  
Device Name      : GMP231  
SW Name         : GMP231  
SW version      : 1.1.0.1537
```

Show Probe Uptime

Use the **TIME** command to show how long the probe has been in operation, and what is the current uptime since last reset (in seconds). The operation counter is in format dddd:hh:mm:ss. Full days and hours are retained in the counter, minutes and seconds are cleared at reset.

TIME<cr>

Example (cumulative uptime 23 hours, 56 minutes, and 49 seconds, uptime since last reset 3409 seconds):

```
time  
00000:23:56:49 Up time: 3409 s
```

Show Command List

Use the **HELP** command to show a list of the currently available serial commands.

HELP<cr>

Example (shows basic commands, advanced commands are not enabled):

```
CLOSE
ECHO
ENV
ERRS
FORM
HELP
INTV
PASS
R
RESET
S
SDELAY
SEND
SERI
SMODE
SNUM
STANDBY
SYSTEM
TIME
VERS
```

Serial Line Output Commands

Start Measurement Output

Use the **R** command to start the continuous outputting of measurement values as an ASCII text string to the serial line.

R<cr>

Example (measurement message in default format):

```
r
CO2= 490 ppm
CO2= 490 ppm
CO2= 491 ppm
CO2= 491 ppm
CO2= 491 ppm
...
```

The probe keeps outputting measurement messages at the interval that has been set **INTV** command until stopped.

Stop Measurement Output

You can stop the measurement output by pressing the **ESC** key or with the **S** command.

Set Output Interval

Use the **INTV** command to change the output interval of the automatically repeating measurement messages. The measurement messages are repeated in the **RUN** mode, or after the **R** command has been given.

```
INTV [n xxx]<cr>
```

where

n = time interval, range 0 ... 255
xxx = time unit = "S", "MIN", or "H"

The shortest output interval (with n = 0) outputs the measurement messages as quickly as the probe's internal measurement cycle produces them, without additional delay.

Example:

```
intv 5 s  
Output interval       : 5 S
```

Output a Reading Once

Use the **SEND** command to output a single measurement message.

```
SEND<cr>
```

Example:

```
send  
CO2= 1702 ppm
```

Set Measurement Output Format

Use the serial line command **FORM** to change the measurement message sent by the probe. You can freely define the output message to include the desired parameters, formatting options, text strings, and additional fields.

FORM [*modifier string*]<cr>

where

modifier string = String of parameters and modifiers that defines the output format, length 1 ... 150 characters.
See Table 9 and Table 10 below. Maximum length may be shorter when text strings are used.

You can return to the default format using the "**FORM /**" command.

Table 9 FORM Command Parameters

Measured Parameter	Abbreviation in FORM Command
Carbon dioxide in ppm	CO2
Carbon dioxide in percent	CO2%
Currently used temperature compensation value	TCOMP
Currently used pressure compensation value	PCOMP
Currently used oxygen concentration compensation value	O2COMP
Currently used relative humidity compensation value	RHCOMP

Table 10 FORM Command Modifiers

Modifier	Description
x.y	Length modifier (number of digits and decimal places)
#t	Tabulator
#r	Carriage-return
#n	Line feed
""	String constant, length 1 ... 15 characters
#xxx	ASCII code value (decimal) of a special character; for example, #027 for ESC
ADDR	Probe address (0 ... 254)
SN	Probe serial number
TIME	Cumulative operating hours of the probe.
Ux	Shows the name of the measurement unit using "x" number of characters. For example, U3 shows the name of the measurement unit with three characters
CS4	Modulus-65536 checksum of message sent so far, ASCII encoded hexadecimal notation
CSX	NMEA xor-checksum of message sent so far, ASCII encoded hexadecimal notation

FORM Command Examples

Example of default output (continuous output from RUN mode):

```
CO2= 860 ppm
CO2= 861 ppm
CO2= 861 ppm
...
```

Command to set output format as %CO₂:

```
form 3.1 "CO2=" CO2% " " U4 #r #n
```

Output example:

```
CO2= 5.1 %CO2
CO2= 5.1 %CO2
CO2= 5.0 %CO2
...
```

Command to set output format as CO₂ ppm with Modulus-65536 checksum:

```
form 6.0 "CO2=" CO2 " " U3 " " CS4 #r #n
```

Output example:

```
CO2= 3563 ppm 9F
CO2= 3562 ppm 9E
CO2= 3559 ppm A4
...
```

Command to set output format as CO₂ ppm, with **start of text** (ASCII character 002) and **end of text** (003) ASCII codes, and without line feed and carriage return at the end:

```
form #002 6.0 "CO2=" CO2 " " U3 #003
```

Output example (ASCII codes not visible here):

```
CO2= 866 ppm CO2= 866 ppm CO2= 867 ppm CO2= 867 ppm
CO2= 867 ppm CO2= 868 ppm CO2= 868 ppm CO2= 869 ppm
...
```

Changing Measurement Settings

Set Compensation Modes

You can change the mode of each environmental compensation type using a dedicated serial command. The commands are:

- **PCMODE** for pressure compensation mode.
- **TCMODE** for temperature compensation mode.
- **O2CMODE** for oxygen compensation mode.
- **RHCMODE** for relative humidity compensation.

Command syntax is as follows:

PCMODE [*on* | *off* | *measured*]<cr>

TCMODE [*on* | *off* | *measured*]<cr>

O2CMODE [*on* | *off*]<cr>

RHCMODE [*on* | *off*]<cr>

where

on = Compensation enabled using setpoint value.
off = Compensation disabled, neutral value used.
measured = Compensation enabled using internal measurement.
Available only for pressure and temperature compensations.

Example (check temperature compensation mode):

```
pass 1300
tcmode
T COMP MODE          : ON
```

Example (change temperature compensation mode to use internal measurement):

```
pass 1300
tcmode measured
T COMP MODE          : MEASURED
```

Change Compensation Setpoint Values

Use the **ENV** command to show or set the setpoint values of the environmental compensation parameters. To change a value, give the parameter name and value as arguments to the **ENV** command.

ENV [*temp|pres|oxy|hum|xtemp|xpres|xoxy|xhum*] [*value*]<cr>

There are four compensation parameters. Values of the parameters are stored in two places: eeprom (non-volatile memory, values retained during power off) and RAM (volatile memory that loses the values when probe is reset, and where values are loaded from non-volatile memory at startup). As the number of writes to eeprom is limited to 30000 cycles by memory implementation, you must write all continuously updated values to RAM to avoid wearing out the eeprom. A second set of parameters (with X prefix in the name) is provided for this purpose.

When writing permanent values to eeprom, use these parameter names. Note that updating these parameters does not update the parameters in RAM (the values that are currently used by the probe).

temp = Compensation temperature. Range -40 ... 100 °C.
pres = Compensation pressure. Range 500 ... 1150 hPa.
oxy = Oxygen content of background gas. Range 0 ... 100%.
hum = Relative humidity of background gas. Range 0 ... 100%.

When writing to RAM, use the parameter names below. The ranges are the same as for the permanent parameters.

xtemp = Compensation temperature that is stored in RAM.
xpres = Compensation pressure that is stored in RAM.
xoxy = Oxygen content of background gas that is stored in RAM.
xhum = Relative humidity of background gas that is stored in RAM.

Example (Show current compensation values; all compensations are enabled. Note that temperature and pressure compensations use internal measurement, so the value in use is constantly changing):

```
env  
Temperature (C)      : 37.00  
Pressure (hPa)      : 1013.20  
Oxygen (%O2)        : 19.70  
Humidity (%RH)      : 93.00
```

```
In use:  
Temperature (C)      : 23.10  
Pressure (hPa)      : 1011.28  
Oxygen (%O2)        : 19.70  
Humidity (%RH)      : 93.00
```

Example below sets temperature compensation to setpoint mode, and changes temperature setpoint value to 37.2 in RAM.

```
pass 1300
tcmode on
T COMP MODE           : ON
env xtemp 37.2
In eeprom:
Temperature (C)       : 37.00
Pressure (hPa)        : 1013.20
Oxygen (%O2)          : 19.70
Humidity (%RH)        : 93.00

In use:
Temperature (C)       : 37.2
Pressure (hPa)        : 1013.20
Oxygen (%O2)          : 19.70
Humidity (%RH)        : 93.00
```

NOTE

If temperature and pressure compensations are configured to use internally measured values, they will continuously update the values in RAM, overriding any temperature and pressure values that are written to RAM with the ENV command.

Set Measurement to Standby Mode

Use the **STANDBY** command to set the probe to standby mode. In standby mode, the CO₂ measurement is disabled. Probe returns to the normal measurement when the command **STANDBY OFF** is given or the probe is reset.

STANDBY [*on* | *off*]<cr>

Example (enable standby mode):

```
standby on
Standby mode           : ON
```

Configuring Serial Line Operation

Set Serial Line Operating Mode

Use the **SMODE** command to set the start-up operating mode of the serial line.

SMODE [*mode*]**<cr>**

where

mode = STOP, RUN, or POLL.

Table 11 Selection of Output Modes

Mode	Measurement Output	Available Commands
STOP	Only with the SEND command.	All (default mode).
RUN	Automatic output.	Only command S .
POLL	Only with the SEND [<i>addr</i>] command.	SEND [<i>addr</i>] and OPEN [<i>addr</i>]. Other commands available after opening a line to the probe using the OPEN command. Use with RS-485 buses where multiple probes can share the same line.

Selected output mode will be activated at next reset or power up.

Example:

```
smode poll
Serial mode      :      POLL
```

Set Serial Line Settings

Use the **SERI** command to set the serial line settings. The new settings will be taken into use when the probe is reset or powered up.

SERI [*b p d s*]<cr>

where

b = baud rate (9600, 19200, or 19200)
p = parity (n = none, e = even, o = odd)
d = data bits (7 or 8)
s = stop bits (1 or 2)

Example (shows default settings):

```
seri
Com1 Baud rate      : 19200
Com1 Parity         : N
Com1 Data bits      : 8
Com1 Stop bits      : 1
```

Example (set serial line to 9600 baud, even, 7 data bits, and 1 stop bit):

```
seri 9600 e 7 1
OK
seri
Com1 Baud rate      : 9600
Com1 Parity         : E
Com1 Data bits      : 7
Com1 Stop bits      : 1
```

Set Probe Address

Use the **ADDR** command to set the device address of the probe. Addresses are required for POLL mode.

ADDR [*aaa*]<cr>

where

aaa = Device address of the probe, range 0 ... 254 (default = 0)

Example (change probe address to 52):

```
pass 1300
addr 52
Address      : 52
```


Set Serial Line Response Time

With the **SDELAY** command you can set delay (response time) of the serial line, or view the currently set delay value.

SDELAY [*delay*]
<cr>

where

delay = Serial line delay, range 0 ... 255 (milliseconds).

Example (set delay to 50 milliseconds):

```
sdelay 50  
Serial delay      :          50
```

Set Serial Line Echo

Use the **ECHO** command to enable or disable the echoing of characters received by the probe.

ECHO [*on/off*]
<cr>

Example:

```
echo  
Echo              : OFF
```

Calibration Commands

NOTE

Before calibrating GMP231 using serial line commands, read the instructions in section Calibration and Adjustment on page 74.

Make sure that the environmental compensation settings of the GMP231 are properly set for your calibration environment; see section Changing Measurement Settings on page 35.

Adjust CO₂ Measurement

Use the **CCO2** command to adjust CO₂ measurement in one or two points. You can use either a low or high concentration reference (one-point adjustment), or both (two-point adjustment).

The idea is to let the probe stabilize in the desired CO₂ concentration, and then input the real CO₂ concentration using the **CCO2** command. If you are performing a two-point correction, repeat for the second point. Then commit the adjustment by giving the **CCO2 -SAVE** command. Note that successfully saving the adjustment clears the calibration date (**CDATE**) and calibration text (**CTEXT**) that have been stored in the probe. Use those commands to enter a new calibration date and text.

```
CCO2 [-lo | -hi] [co2] <cr>
```

```
CCO2 [-save | -cancel]<cr>
```

```
CCO2 [-reset]<cr>
```

where

- lo* = Select low concentration for adjustment. Adjusts measurement offset.
- hi* = Select high concentration for adjustment. Adjusts measurement gain.
- co2* = CO₂ concentration reference in ppm.
- save* = Save currently entered adjustments.
- cancel* = Cancel currently entered adjustments.
- reset* = Clear user adjustments, set Gain to 1 and offset to 0.

Example (show current user adjustment status – no adjustment done):

```
pass 1300
cco2
1.Ref. point low      0
1.Meas. point low    0
2.Ref. point low    200000
2.Meas. point low    200000
Gain                  : 1.0000
Offset                : 0.0000
```

Example (one-point adjustment in 5% concentration (50000 ppm)):

```
pass 1300
cco2 -lo 50000
OK
cco2 -save
OK
```

Set Calibration Date

Use the **CDATE** command to view the date when the probe was last calibrated, or set a new date.

```
CDATE [yyyy mm dd]<cr>
```

where

```
yyyy = Year of calibration in four digits
mm   = Month of calibration in two digits
dd   = Day of calibration in two digits
```

Example (show currently stored calibration date):

```
>pass 1300
>cdat
Calibration date      : 2013-10-03
```

Example (set calibration date to 2014-03-10):

```
>pass 1300
>cdat 2014 03 10
Calibration date      : 2014-03-10
```

Set Calibration Info Text

Use the **CTEXT** command to view or set calibration information text.

```
CTEXT [text]<cr>
```

where

text = Calibration information text string, max 19 characters. If you want to use spaces in the string, enclose the text in quotes.

Example (shows the text “Calibrated at” followed by the currently stored calibration text):

```
pass 1300  
ctext  
Calibrated at Vaisala
```

Example (set calibration text to “Lab_1”):

```
pass 1300  
ctext Lab_1  
Calibrated at Lab_1
```

Adjust Temperature Measurement

Use the **CT** command to perform an offset correction to the internal temperature measurement. The correction is done by providing the correct temperature as an argument to the **CT** command.

```
CT [temp]<cr>
```

```
CT [-reset]<cr>
```

where

temp = Correct temperature in degrees Celsius (°C).

Example (adjust the internal temperature measurement to 23 °C at the current conditions):

```
pass 1300  
ct 23  
OK
```

Example (clear the offset adjustment from internal temperature measurement):

```
pass 1300  
ct -reset  
OK
```

Adjust Pressure Measurement

Use the **CP** command to perform an offset correction to the internal pressure measurement. The correction is done by providing the correct pressure as an argument to the **CP** command.

```
CP [pressure]<cr>
```

```
CP [-reset]<cr>
```

where

pressure = Correct pressure in hectopascals (hPa).

Example (adjust the internal pressure measurement to 990 hPa at the current conditions):

```
pass 1300  
cp 990  
OK
```

Example (clear the offset adjustment from internal pressure measurement):

```
pass 1300  
cp -reset  
OK
```

Configuring Analog Output

Set Analog Output Scaling

Use the **ASEL** command to show or set the scaling of the analog output.

```
ASEL [channel] [parameter lowlimit highlimit]<cr>
```

where

channel = Analog output channel, only 1 can be selected.

parameter = Parameter that is output on analog channel.
Only parameter available is CO2.

lowlimit = Lower limit of channel scaling in ppm.

highlimit = High limit of channel scaling in ppm.

Example (change channel scaling to 0 ... 5%):

```
pass 1300  
asel 1 co2 0 50000  
Aout 1 quantity : CO2(0 ... 50000)
```

Set Analog Output Mode

Use the **AMODE** command to set the analog output limits and error level.

```
AMODE [channel lo_value hi_value error_value]<cr>
```

where

channel = Analog output channel, only 1 can be selected.

lo_value = Low limit of the channel.

hi_value = High limit of the channel.

error_value = Error value of the channel.

Example (show current configuration):

```
pass 1300  
amode 1  
Aout 1 range (mA) :4.00 ... 20.00 (error :21.00)
```

Example (set channel to 4 ... 20 mA, and error level to 3.6 mA):

```
pass 1300  
amode 1 4 20 3.6  
Aout 1 range (mA) :4.00 ... 20.00 (error : 3.60)
```

Set Analog Output Clipping and Error Limit

Use the **AOVER** command to define the behavior of the analog output when the measured value is outside the scaled output range.

```
AOVER [channel clip% valid%]<cr>
```

where

channel = Analog output channel, only 1 can be selected.
clip% = Output margin (%) at which the output is clipped.
valid% = Output margin (%) at which the output of the channel goes into the error state. The error state is defined using the **AMODE** command, see section Set Analog Output Mode on page 45.

For example, first check the analog output settings using **ASEL**, **AMODE**, and **AOVER** commands:

```
pass 1300  
asel 1  
Aout 1 quantity      : CO2(0 ... 50000)  
  
amode 1  
Aout 1 range (mA)    :0.00 ... 20.00 (error : 23)  
  
aover 1  
Aout 1 clipping      :10.00 %  
Aout 1 error limit   :10.00 %
```

Now give the following **AOVER** command:

```
aover 1 5 10  
Aout 1 clipping      : 5.00 %  
Aout 1 error limit   :10.00 %
```

The analog output now behaves like this:

- Clipping is now set to 5%, meaning the output is allowed to vary between 0 ... 21 mA. The analog channel will output the measurement for 0 ... 52500 ppm, but range 0 ... 20 mA remains scaled to 0 ... 50000 ppm.
- Error limit is 10%, which means the output will show the error state (23 mA) when the measured value is 10% outside the scaled output range. With the settings above, this will happen if the measured CO₂ concentration is outside range 0 ... 55000 ppm.
- The output will never actually be between 21 mA and 23 mA because of clipping.

Test Analog Output

You can test the operation of the analog output with the **ATEST** command by forcing the output to a given value. You can then measure the output with a calibrated multimeter. After testing the output, use the **ATEST** command again to exit the test mode.

```
ATEST [channel] [level]<cr>
```

where

channel = Analog output channel, only 1 can be selected.
level = Level for analog output channel in mA.

Example (enable analog output test mode, set level to 20 mA):

```
pass 1300  
atest 1 20  
Aout 1 (mA) :20.000
```

Example (disabling analog output test mode, resuming normal output):

```
atest 1  
Aout 1 test mode disabled.
```

Other Commands

Enable Advanced Commands

Use the **PASS** command to enable advanced serial commands. Advanced commands can be used until the next reset.

```
PASS [code]<cr>
```

where

code = Code for enabling advanced commands (1300).

Example:

```
pass 1300
```


Connecting to Probe in POLL Mode

Use the **OPEN** command to connect to a probe that is in POLL mode.

```
OPEN [address]<cr>
```

where

address = Probe address, range 0 ... 254.

Example (target probe in POLL mode, with address 52):

```
open 52  
GMP231: 52 Opened for operator commands
```

Closing the Connection to a Probe in POLL Mode

The **CLOSE** command closes the connection to a probe.

```
CLOSE<cr>
```

Example:

```
close  
line closed
```

Show Active Errors

Use the **ERRS** command to display probe error messages. The possible errors and their identifying numbers correspond to content of the status word of the I²C interface. See section Status Word on page 57.

```
ERRS<cr>
```

Example (showing normal status, no active errors):

```
errs  
NO CRITICAL ERRORS  
NO ERRORS  
NO WARNINGS  
STATUS NORMAL
```

Example (showing probe in standby mode, no active errors):

```
errs  
NO CRITICAL ERRORS  
NO ERRORS  
NO WARNINGS  
STATUS 25 : Device in standby mode (set by user)
```

Reset Probe

Use the **RESET** command to reset the probe.

RESET<cr>

When the **RESET** command is given, the probe will restart as if it had just been powered on.

Restore Factory Settings

Use the **FRESTORE** command to restore the probe to its factory configuration. All user settings will be lost.

FRESTORE<cr>

NOTE

After using the **FRESTORE** command, reset the probe using the **RESET** command.

Example:

```
pass 1300
frestore
Parameters restored to factory defaults
reset
```

```
GMP231 - Version 1.1.0
Vaisala Oyj 2012 - 2014
```

CHAPTER 5

I²C INTERFACE

This chapter describes the I²C interface implementation of the GMP231.


Overview

GMP231 has an inter-integrated circuit (I²C) interface for interfacing with the incubator's control computer. GMP231 implements I²C slave functionality, with the incubator's computer acting as the master. The interface can be used to read measurement values and status information, set operation parameters, and make adjustments.

Physical Interface

The physical interface is a non-isolated 3-wire interface. Wires are SDA, SCL and ground. SDA and SCL lines are buffered. Ground is shared with power supply. There are small pull-up resistors for SCL and SDA. Connector is 8 pin male M12. Maximum cable length should not exceed 5 m and maximum capacitance between communication lines and ground should not exceed 500 pF.

For connector pinout and wiring information, see section Wiring on page 24.



1403-149

Figure 12 Hardware Schematic

Communication Parameters

GMP231 supports maximum 50 kHz clock speed. Protocol bits are sent most significant bit (MSB) first. Parameter bytes are sent using little endian order.

Addressing

GMP231 uses 7-bit addressing. The address consists of:

- 4-bit device type identifier part (default “0001” for GMP231)
- 3-bit sub address (default “001”)

The full 7-bit default address is “0001001” (09h). In I²C communication, the address should be provided by the master in the standard way after the I²C start condition, with the read/write bit as the least significant bit (LSB).

Table 12 GMP231 I²C Address

0	0	0	1	0	0	1	R/W
Device type				Sub-address			Read/write bit (LSB)

The I²C implementation of the GMP231 also includes the address inside the message frame. The purpose of this is to make the I²C implementation easier, since the I²C address can be lost by the I²C hardware. This address is provided without the read/write bit, with zero as the MSB.

Table 13 GMP231 Device Address

0	0	0	0	1	0	0	1
MSB	Device type				Sub-address		

NOTE

Make sure there are no addressing conflicts if other I²C devices are put on the same bus. The GMP231 address can be changed, see Table 40 on page 68.

Communication Flow

Basic communication flow always includes I²C write and read commands. First the master writes a command to the slave device, and then the master reads the results of that command from the slave.

When the master reads data from the slave, there is an ACK/NACK-bit in the status byte that informs the master whether or not communication was success. ACK is defined as zero and NACK is defined as one in the logical level.

NOTE

This ACK/NACK refers to the message level acknowledgement. I²C protocol includes a separate byte level acknowledgement.

Command messages sent by the master are called **invokes**. Replies sent by the slave are called **responses**. Note that also responses include the device address.

Table 14 Invoke Message in GMP231 I²C Interface

Message Segment	Length	Content
Start		I ² C start condition.
I ² C address	1 byte	See Table 12 on page 51.
Command	1 byte	Identifier of command.
Device address	1 byte	See Table 13 on page 51.
Frame length	1 byte	Length of invoke message in bytes (excluding I ² C address, including CRC). Minimum invoke frame length is 5 bytes.
Data	Variable length	Content and length depending on the command. May be left out if the command contains no data in the invoke message.
Checksum	2 bytes	See section Checksum on page 56.
Stop		I ² C stop condition

Table 15 Response Message in GMP231 I²C Interface

Message Segment	Length	Content
Start		I ² C start condition.
I ² C address	1 byte	See Table 12 on page 51.
Status	1 byte	See section Status Byte on page 56.
Command	1 byte	Identifier of command that was used in the invoke that the slave is responding to. If the slave is in Idle state (no valid invoke), the command code is FFh.
Device address	1 byte	See Table 13 on page 51.
Frame length	1 byte	Length of response message in bytes (excluding I ² C address, including CRC). Minimum response frame length is 6 bytes.
Data	Variable length	Content and length depending on the command.
Checksum	2 bytes	See section Checksum on page 56.
Stop		I ² C stop condition


GMP231 State Machine

The main and initial state of the GMP231 is Idle, and it will change to WaitResponse state only when a valid invoke is received. In the WaitResponse state, the GMP231 expects to see an I²C read operation from the master. After seeing a read operation, the GMP231 outputs its response with ACK/NACK and status signals.

If GMP231 is in WaitResponse state and master sends a new invoke, the GMP231's response to the previous invoke is lost. When the master sends the next I²C read command, the GMP231 sends it the response to the latest invoke.

If GMP231 is in Idle state and the master sends an I²C read, GMP231 responds with a NACK-signal. This tells the master that the data which the master may have received in same I²C read is not valid.

If the GMP231 receives an invalid invoke, it goes to the Idle state. An invoke message can be invalid because of an unknown command, erroneous CRC, or invalid message length.



1403-146


Figure 13 GMP231 State Machine

Examples of Communication Flow

The basic data transfer communication flows are presented in the figures below. Each arrow represents an I²C read or write operation. The examples are simplified presentations. For actual message content, see section Commands on page 59.

For example, Figure 14 below shows the following message sequence:

1. The master invokes the Get_Parameter command to read the CO₂ parameter using an I²C write operation. This command prepares the slave to wait for a read operation from the master.
2. The master begins an I²C read operation to read the results of the Get_Parameter CO₂ command. The slave sends the requested CO₂ result and an ACK signal to the master.



1403-116

Figure 14 Get_Parameter with ACK




Figure 15 Set_Parameter with ACK




Figure 16 Get_Parameter with NACK




Figure 17 Get_Parameter with Alarm

NOTE

The alarm can be any of the state bits in the status byte.

Timing

The minimum time delay that the master must wait between the invoke and response messages depends on the operation. If the operation includes a write to the non-volatile memory, it takes more time than other operations.

Table 16 **Timing**

Operation	Minimum delay
Normal delay between invoke and response	10 ms
Delay when write to non-volatile memory	300 ms

Status Byte

The status byte gives the master device information about the slave device's state, and information about the communication status with the ACK/NACK bit.

The status byte has bits for signaling Status, Warning, Error and Critical error statuses. These bits are cleared when the status word is read. Bits are set when the corresponding status or error state changes in the slave device.

Table 17 **Status Byte**

Bit#	Description
0	ACK/NACK
1	Critical error
2	Error
3	Warning
4	Status
5	
6	
7	

Checksum

GMP231 uses a CRC16-CCITT checksum in its protocol frame. CCITT (x.25) polynomial is $X^{16}+X^{12}+X^5+1 = 11021h$. Initial value is 0000h and the final value is XORed with FFFFh. The checksum uses a bit reversed algorithm.

When the invoke message is received, the checksum is calculated using bytes from the command byte to the last byte of the data field. The checksum needs to be valid before data can be accepted. If the checksum is not valid, the message is rejected and the internal state of the GMP231 is set to Idle.

When the response message is transmitted, the checksum is calculated using bytes from the status byte to the last byte of the data field.

Status Word

The status word is used to monitor the status of the GMP231 device. It can be read in the same way as any other slave parameter. The status word is used as a 32-bit long bit field, where each bit represents a state of some error or other essential status. The status word is sent least significant bit (LSB) first.

The status word content is updated every two seconds. Changes in the status word bits can be monitored by reading the status byte. See section Status Byte on page 56.

The content of the status word is listed in Table 18 on page 58. The status bits are categorized according to the severity of the status:

- **Critical errors** are fatal to the operation of the unit. It may not be able to respond to communication at all, and will not measure correctly.
- **Errors** prevent CO₂ measurement and cause the analog outputs to be set to the error state. Depending on the problem, errors may resolve themselves. For example, sensor heating will eventually dry out condensation on the optical surfaces.
- **Warnings** do not prevent normal operation but may indicate possible problems.
- **Status** indicates a known state of the unit, such as the CO₂ measurement standby mode.

NOTE

There are several possible internal error statuses that you cannot do much about. In addition to the recommendations in Table 18 on page 58 and in section Problem Situations on page 84, try to power cycle the probe and see if the error stays on.

If your unit has persistent errors that you cannot resolve yourself, contact Vaisala. See sections Technical Support on page 85 and Product Returns on page 85.

Table 18 Status Word Content

Bit#	Type	Meaning	Recommended Action
0	Critical Error	Program memory corrupted (CRC error).	Fatal error, contact Vaisala.
1	Critical Error	Parameter memory corrupted (CRC error).	Fatal error, contact Vaisala.
2	Reserved		
3	Reserved		
4	Error	Low supply voltage error.	Check supply voltage.
5	Error	Low internal 30 V voltage.	
6	Error	Low input signal. Can be caused by dirt or condensation on the optical surfaces.	Wait to see if condensation is removed by heat. For cleaning instructions, see section Cleaning on page 71.
7	Error	Low internal 8 V voltage.	
8	Error	Signal dynamic range too high.	
9	Error	Pressure sensor communication.	
10	Error	Pressure sensor out of range.	
11	Error	Sensor temperature too high for operation.	Wait for sensor to cool down.
12	Error	CO ₂ concentration too high to measure.	Wait for CO ₂ concentration to fall into the measurable range.
13	Error	Sensor heater resistance out of range.	
14	Error	IR source temperature error too high.	
15	Reserved		
16	Error	Internal 2.5 V voltage out of range.	
17	Error	Internal 1.7 V voltage out of range.	
18	Error	Low IR current.	
19	Reserved		
20	Warning	Low input signal. Can be caused by dirt or condensation on the optical surfaces.	Continue normally.
21	Reserved		
22	Warning	Noisy signal.	Continue normally.
23	Warning	Transmitter reset by watchdog process.	Continue normally.
24	Status	CO ₂ measurement in standby mode: set automatically due to high temperature.	Wait for sensor to cool down.
25	Status	CO ₂ measurement in standby mode: set by user command.	Set to normal mode when desired.
26	Status	CO ₂ adjustment state on.	Complete the CO ₂ adjustment.
27	Reserved		
28	Reserved		
29	Reserved		
30	Reserved		
31	Reserved		

Commands

Get_Interface_Version

Get_Interface_Version command (ID 80h) reads the interface version information. This command is recommended for verifying version compatibility before reading or writing parameters.

Table 19 Get_Interface_Version Invoke Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (write)
Command ID	1 byte	Always 80h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Always 05h
Checksum	2 bytes	See section Checksum on page 56

Table 20 Get_Interface_Version Response Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (read)
Status	1 byte	See section Status Byte on page 56
Command ID	1 byte	Always 80h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Always 0Ah
Data	1 byte	Device version
	1 byte	Protocol frame version
	1 byte	Command set version
	1 byte	Parameter set version
Checksum	2 bytes	See section Checksum on page 56

Get_Parameter

Get_Parameter command (ID 81h) reads parameter values. You can use it to read both measurement results and operational parameters. If the master tries to read more bytes than message size, the slave sends FFh bytes.

Table 21 Get_Parameter Invoke Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (write)
Command ID	1 byte	Always 81h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Always 06h
Data	1 byte	ID of parameter to be read
Checksum	2 bytes	See section Checksum on page 56

Table 22 Get_Parameter Response Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (read)
Status	1 byte	See section Status Byte on page 56. If requested parameter ID was unknown, NACK bit is set in the status byte.
Command ID	1 byte	Always 81h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Varies according to data length, 07h ... 39h.
Data	1 byte	ID of parameter
	1 ... 50 bytes	Value of parameter. If requested parameter ID is unknown, these data bytes are left out of the response.
Checksum	2 bytes	See section Checksum on page 56

Example: Read CO₂ Measurement Result

Table 23 Get_Parameter Invoke Message Example

Message Bytes (hex)	Content
12	I ² C address
81	Get_parameter command
09	Device address
06	Frame length
0A	CO2 Parameter ID
AA	CRC high
9F	CRC lo

Table 24 Get_Parameter Response Message Example

Message Bytes (hex)	Content
13	I ² C address
00	Status byte (no errors, ACK)
81	Get_parameter command
09	Device address
0B	Frame length
0A	CO2 Parameter ID
69	CO2 value 653.6314 ppm
68	
23	
44	
75	CRC high
7D	CRC lo

Set_Parameter

Set_Parameter command (ID 82h) writes parameter values to non-volatile memory. You can use it to set the operational parameters of the GMP231. Depending on the change, the functionality of the GMP231 may not change immediately.

The length of the invoke message varies depending on the data length. The master must write as many bytes as indicated in the frame length of the invoke message. If the master tries to write a longer or shorter message, GMP231 rejects the message.

Table 25 Set_Parameter Invoke Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (write)
Command ID	1 byte	Always 82h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Varies according to data length, 07h ... 38h.
Data	1 byte	Parameter ID
	1 ... 50 bytes	Parameter value
Checksum	2 bytes	See section Checksum on page 56

Table 26 Set_Parameter Response Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (read)
Status	1 byte	See section Status Byte on page 56.
Command ID	1 byte	Always 82h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Always 08h.
Data	1 byte	Parameter ID
	1 byte	Return code. See Table 27 below.
Checksum	2 bytes	See section Checksum on page 56

Table 27 Set_Parameter Return Codes

Code	Meaning
0	Ok
1	Unknown parameter ID
2	Not writeable parameter
3	Value field too long
4	Value field too short
5	Data value not accepted

Example: Set Compensation Temperature

Table 28 Example Set_Parameter Invoke Message

Message Bytes (hex)	Content
12	I ² C address
82	Set_parameter command
09	Device address
0A	Frame length
10	Parameter ID of compensation temperature
00	Temperature 37C
00	
14	
42	
0C	
6E	CRC lo

Table 29 Example Set_Parameter Response Message

Message Bytes (hex)	Content
13	I ² C address
04	Status byte (error active, ACK)
82	Set_parameter command
09	Device address
08	Frame length
10	Parameter ID of compensation temperature
00	Return code: Ok
D1	CRC high
CE	CRC lo

Get_Parameter_Info

Get_Parameter_Info command (ID 83h) reads the properties of a single parameter from the GMP231. The command is useful for adapting to parameters that have been added in a new software version. If the requested parameter ID is not valid, data type **Unknown Parameter ID** is returned.

Table 30 Get_Parameter_Info Invoke Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (write)
Command ID	1 byte	Always 83h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Always 06h.
Data	1 byte	Parameter ID
Checksum	2 bytes	See section Checksum on page 56

Table 31 Get_Parameter_Info Response Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (read)
Status	1 byte	See section Status Byte on page 56.
Command ID	1 byte	Always 83h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Always 12h.
Data	1 byte	Parameter ID
	1 byte	Parameter datatype. See Table 32 below.
	1 byte	Parameter length in bytes.
	1 byte	Parameter persistence. Describes if the parameter value is volatile (lost at reset) or non-volatile (survives reset). See Table 33 below.
	8 bytes	Parameter name. If name is shorter than 8 bytes, extra bytes are filled with 00h.
Checksum	2 bytes	See section Checksum on page 56

Table 32 Parameter Data Types

Code	Meaning
0	Unknown parameter ID
1	Byte
2	Integer (16-bit)
3	Unsigned Integer (16-bit)
4	Float (32-bit)
5	String

Table 33 Parameter Persistence

Code	Meaning
0	Void
1	Volatile
2	Non volatile

Adjust

Adjust command (ID 84h) controls the user adjustment sequence of CO₂ measurement.

Table 34 Adjust Invoke Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (write)
Command ID	1 byte	Always 84h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Varies according to data length, 07h ... 0Bh.
Data	1 byte	Adjustment subcommand. See Table 36 below.
	1 byte	Parameter to be adjusted. See Table 37 below.
	4 bytes	Value of parameter. Used only with subcommands 2 and 3.
Checksum	2 bytes	See section Checksum on page 56

Table 35 Adjust Response Message

Message Segment	Length	Content
I ² C address	1 byte	I ² C address (read)
Status	1 byte	See section Status Byte on page 56.
Command ID	1 byte	Always 84h
Device address	1 byte	See Table 13 on page 51
Frame length	1 byte	Always 07h.
Data	1 byte	Return code. See Table 38 on page 66.
Checksum	2 bytes	See section Checksum on page 56.

Table 36 Adjustment Subcommands

Code	Adjustment operation
0	Start 1 point adjustment
1	Start 2 point adjustment
2	Record measured point 1, reference value is given in parameter
3	Record measured point 2, reference value is given in parameter
4	Cancel adjustment (previous adjustment is reverted)
5	End (adjustment is saved and new values are taken in use)
6	Revert to factory calibration (clear user adjustment)

Table 37 Adjustment Parameters

Code	Purpose
0	All parameters (valid with revert to factory calibration)
1	CO ₂

Table 38 Adjustment Return Codes

Code	Meaning
0	Ok
1	Function not supported
2	Sequence error
3	Recorded-Reference difference too large
4	2-point adjustment: Points too close
5	Given reference value is invalid

Adjusting Measurement

NOTE

Before implementing an adjustment sequence using the Adjust command, read the general instructions for calibration and adjustment in section Calibration and Adjustment on page 74.

Create the reference environment inside the chamber, and use the Adjust command to perform the adjustment sequence.

Adjustment can fail for a number of reasons. Refer to the list of return codes for the Adjust command in Table 38 above.

One Point Adjustment

To perform a one point adjustment of carbon dioxide (CO₂), measurement using I²C protocol, you must perform the following sequence:

1. Using the **Adjust** command, start 1 point adjustment for the chosen parameter.
2. Place the sensor in the reference environment and wait until the measurement has stabilized.
3. Using the **Adjust** command, record the measured point and give the reference value.
4. Use the **Adjust** command to end the adjustment.

Two Point Adjustment

To perform a two point adjustment of CO₂ measurement using I²C protocol, you must perform the following sequence:

1. Using the **Adjust** command, start 2 point adjustment for CO₂.
2. Supply the low concentration CO₂ reference gas to the sensor and wait for three minutes until the measurement has stabilized.
3. Using the **Adjust** command, record the first measured point and give the first reference value.
4. Supply the high concentration CO₂ reference gas to the sensor and wait for three minutes until the measurement has stabilized.
5. Using the **Adjust** command, record the second measured point and give the second reference value.
6. Use the **Adjust** command to end the adjustment.

Data Registers

The register table describes all available parameters and their properties. The properties are: parameter meaning, ID, name, data type, length and persistence. Persistence defines if the parameter is saved in eeprom (non-volatile memory) or in RAM. Make sure not to write excessively to the eeprom, as it has a maximum lifetime of approximately 30000 cycles.

Data Formats

Table 39 Data Formats

Data type name	Size (Bytes)	Other
Byte	1	Value range 0...255
Integer	2	Value range -32768...32767.
Unsigned integer	2	Value range 0...65535
Long integer	4	Value range -2,147,483,648...2,147,483,647
Unsigned long integer	4	Value range 0...4,294,967,295
Float	4	According to IEEE-754. Nan (7FC00000) is returned if no value is available.
String	Max. 50	All characters accepted (00h...FFh)

NOTE

Maximum string size refers to maximum communication buffer size. The actual reserved storage space for each parameter can be seen in Table 40 on page 68.

NOTE

Integers and floating point numbers are sent LSB first.

Register Table

Table 40 GMP231 Register Table

Meaning	Name	ID	Size (bytes)	Type	Read/Write	Persistent	Other
Factory information							
Device address	ADDR	0	1	Byte	R	Yes	Default is 09h.
Device serial number	SNUM	1	12	Str	R	Yes	Example: A1234567
Sensor number	SSNUM	2	12	Str	R	Yes	Example: B1234567
Component board number	CBNUM	3	12	Str	R	Yes	Example: C1234567
Software version number	VERS	4	12	Str	R	Yes	Example: 1.2.3.4567
Factory adjustment date Year	ADATEY	5	2	Uint	R	Yes	Example: 2014
Factory adjustment date Month	ADATEM	6	1	Byte	R	Yes	Example: 3
Factory adjustment date Day	ADATED	7	1	Byte	R	Yes	Example: 29
General parameters and variables							
Device status word	STATUS	8	4	Str	R	No	See section Status Word on page 57.
CO2 measurement mode	CO2_MODE	9	1	Byte	R/W	Yes	0 = Standby mode. Measurement and probe heating is off 1 = Measurement on Note: Internal logic can override this setting
Final CO2 result	CO2	10	4	Float	R	No	ppm CO ₂
Raw CO2 (uncompensated, unfiltered)	CO2_RAW	11	4	Float	R	No	ppm CO ₂
Compensated CO2 (unfiltered)	CO2_COMP	12	4	Float	R	No	ppm CO ₂
CO2 measurement filtering	CO2_FILT	13	1	Byte	R/W	Yes	Range 0 ... 1, 0 = no filtering 1 = filtering (default)
Sensor heating	HEAT	14	1	Byte	R/W	Yes	Range 0...1 0 = no heating 1 = heating (default)

Meaning	Name	ID	Size (bytes)	Type	Read/Write	Persistent	Other
Compensation settings							
Temperature compensation mode	TC_MODE	15	1	Byte	R/W	Yes	0 = Compensation off 1 = Use temperature setpoint value (default) 2 = Use Internal sensor temperature
Compensation temperature	T_COMP	16	4	Float	R/W	No	Celsius
Measured temperature (internal sensor)	T	17	4	Float	R	No	Celsius
Pressure compensation mode	PC_MODE	18	1	Byte	R/W	Yes	0 = Compensation off 1 = Use pressure setpoint value 2 = Use internal pressure sensor (default)
Compensation pressure	P_COMP	19	4	Float	R/W	No	hPa
Measured pressure (internal sensor)	P	20	4	Float	R	No	hPa
Humidity compensation mode	RHC_MODE	21	1	Byte	R/W	Yes	0 = Compensation off 1 = Use RH setpoint value (default)
Compensation Humidity	RH_COMP	22	4	Float	R/W	No	%RH
Oxygen compensation mode	O2C_MODE	23	1	Byte	R/W	Yes	0 = Compensation off 1 = Use oxygen concentration setpoint value (default)
Compensation Oxygen	O2_COMP	24	4	Float	R/W	No	%O2
Adjustment settings							
Reference CO2 point 1	CO2_RP1	25	4	Float	R/W	Yes	ppm CO ₂ 0 ppm
Measured CO2 point 1	CO2_MP1	26	4	Float	R	Yes	ppm CO ₂ 0 ppm
Reference CO2 point 2	CO2_RP2	27	4	Float	R/W	Yes	ppm CO ₂ 20%
Measured CO2 point 2	CO2_MP2	28	4	Float	R	Yes	ppm CO ₂ 20%
Reference temperature point 1	T_RP1	29	4	Float	R/W	Yes	Celsius 0C
Measured temperature point 1	T_MP1	30	4	Float	R	Yes	Celsius 0C
Reference pressure point 1	PRE_RP1	31	4	Float	R/W	Yes	hPa 1013.25
Measured pressure point 1	PRE_MP1	32	4	Float	R	Yes	hPa 1013.25
Analog output settings							
Analog output mode	A_MODE	33	1	Byte	R/W	No	0 = Off (0 mA) 1 = Testmode 2 = Normal (default) 3 = Locked to latest value
Analog output test current	A_TC	34	4	Float	R/W	No	0 ... 25 mA
Analog output error state current	A_EC	35	4	Float	R/W	Yes	0 ... 25 mA
Analog output low end current	A_LC	36	1	Byte	R/W	Yes	0 = 0 mA 1 = 4 mA
Analog output scale low (0/4 mA)	A_LOW	37	4	Float	R/W	Yes	ppm CO ₂
Analog output scale high (20 mA)	A_HI	38	4	Float	R/W	Yes	ppm CO ₂

Meaning	Name	ID	Size (bytes)	Type	Read/Write	Persistent	Other
Other							
Persistent compensation values (used if volatile values are not given)							
Compensation temperature	T_COMP2	39	4	Float	R/W	Yes	37 °C (default)
Compensation pressure	P_COMP2	40	4	Float	R/W	Yes	1013.25 hPa (default)
Compensation Humidity	RH_COMP2	41	4	Float	R/W	Yes	90 %RH (default)
Compensation Oxygen	O2_COMP2	42	4	Float	R/W	Yes	19.7 %O ₂ (default)

CHAPTER 6

MAINTENANCE

This chapter provides information that is needed in the basic maintenance of the GMP231.

Cleaning

When correctly installed, the GMP231 is minimally exposed to contaminants in the chamber. There is little reason to perform cleaning other than normal chamber sterilization, and changing the filter and/or silicone plug if they appear contaminated. See the following sections for instructions:

- Changing the Filter on page 72.
- Changing the Silicone Plug on page 73.

The CARBOCAP[®] sensor of the GMP231 is well protected by the PTFE filter, and it can tolerate some dirt on the optics as the measurement is compensated for the reduction of signal.

CAUTION

When changing the filter, you can use clean instrument air to gently blow any loose dirt and filter material away from the sensor. Do not attempt to clean the optical surfaces of the sensor in any other manner.

Chemical Tolerance

GMP231 tolerates the following sterilization chemicals:

- DMSO
- IPA (70% Isopropyl Alcohol, 30% water)
- H₂O₂ (2000 ppm), non-condensing
- Ethanol
- Acetic acid


CAUTION

The electronics housing of the GMP231 is not sealed, so do not expose it to these chemicals. If necessary, you can clean the housing by wiping with a moist cloth.

Changing the Filter

Change the filter to a new one if it shows visible signs of contamination.

1. Pull the white PTFE filter away from the sensor. Rotating the filter slightly makes it easier to detach.
2. Use clean instrument air to gently blow any loose dirt and filter material away from the sensor.
3. Take a new clean filter and push it onto the sensor. If you are using the Vaisala silicone plug for sealing, push and rotate the filter slightly to make sure the filter reaches below the edge of the plug.




1403-156

Figure 18 **Changing the Filter**

Changing the Silicone Plug

Change the silicone plug if it shows visible signs of contamination. It is best to replace the filter also.

1. Pull the white PTFE filter away from the sensor. Rotating the filter slightly makes it easier to detach
2. Lift one edge of the plug and pull it away from the installation tube.
3. Use clean instrument air to gently blow any loose dirt and filter material away from the sensor.
4. Clean the installation tube and the wall around the plug.
5. Place the new silicone plug over the sensor and push it into the installation tube.
6. Take a new clean filter and push it onto the sensor. Push and rotate the filter slightly to make sure it is fully in place.



1403-157

Figure 19 Changing the Silicone Plug

Calibration and Adjustment

Calibrate and adjust the CO₂ measurement of the GMP231 as needed. Before starting, read through this section completely so that you are aware of your options, and the main factors that affect the result.

NOTE

Performing an accurate calibration and adjustment takes some time and preparation. Instead of doing it yourself, you can also have a Vaisala service center calibrate and adjust your GMP231. For contact information, see section Product Returns on page 85.


NOTE

Calibration means comparing the GMP231 to a known reference, such as calibration gas or a reference instrument. Correcting the reading of the GMP231 so that it measures accurately is referred to as **adjustment**.

Calibration Setup

GMP231 is designed to be calibrated while it remains installed through an incubator wall. If you calibrate the GMP231 without it being installed, note the following:

- If you are using a calibration gas, prevent it from entering the electronics housing of the GMP231. Otherwise it will diffuse through the probe to the sensor and alter the CO₂ reading.
- Make sure the PTFE filter is in place when performing calibration.
- If you are using the calibration adapter accessory to feed the calibration gas to the sensor, note that you must have the silicone plug and the PTFE filter installed on the probe. Without both of them in place, the calibration adapter will not function properly. Vaisala recommends replacing the silicone plug and the PTFE filter before calibration.



1403-147

Figure 20 **Inserting the Calibration Adapter over the Filter**

Using Ambient Air as Reference

You can use ambient air to do a 1-point calibration with the background CO₂ level as your reference. You will need a calibrated reference instrument to compare against, for example a GM70 hand-held meter with a calibrated GMP222 probe.

With the GMP231 and the reference instrument in the same space (for example, inside the incubator with the door open), allow the measurement to stabilize before comparing the readings. Try to provide as stable environment as you can during this time. Avoid working around the incubator during this time.

Using a Calibration Gas as Reference

There are two easy ways to use a calibration gas as a reference:

- You can supply the gas to the GMP231 using the calibration adapter accessory. Gas flow should be in the range 0.5 ... 1.1 l/min, recommendation is 1 l/min. Allow the measurement to stabilize for three minutes before starting the calibration.
- You can fill the entire incubator with the calibration gas.

To perform a two-point adjustment, you need two calibration gases: one gas that is below 2 %CO₂ (low-end reference) and one that is above 2 %CO₂ (high-end reference).

When supplying the gas from a gas bottle, make sure the gas bottle has stabilized to room temperature before starting.

Effect of Environmental Compensations

GMP231 has various environmental compensations that improve its CO₂ measurement accuracy (see section Environmental Compensation on page 17). As the calibration and adjustment environment may differ from the actual measurement environment, you must make sure that the compensation settings are properly set. Here are some key points to remember:

- Pressure and temperature compensations have a significant effect on accuracy. If you are using setpoint values instead of the values from built-in pressure and temperature sensors, make sure to correct the setpoints so that they corresponds to your calibration situation. Consider switching the compensations to use the internal sensors when calibrating, and then switching back when calibration and adjustment is done.

- The effect of background gas compensations for humidity and oxygen may be significant when using calibration gases, since they are often dry and oxygen-free. For example, pure nitrogen gas is typically used as a convenient 0 ppm CO₂ reference.
- Remember to restore the normal compensation settings after completing calibration and adjustment. If you are integrating the calibration functionality of the GMP231 as part of the incubator's control software, also implement proper handling of the environmental compensations.

Limits of Adjustment

GMP231 limits the amount of adjustment that is allowed to the CO₂ measurement. The maximum correction that you can apply is **1000 ppm + 25 %** of the probe's uncorrected reading. Previous user adjustments do not affect this limit (correction is not cumulative). This feature limits the possible error introduced by incorrect adjustment.

For example, if you are adjusting using a 5 %CO₂ calibration gas (50000 ppm), the maximum correction you can apply is approximately 13500 ppm. Attempting to apply a greater adjustment will fail. Notification of failure from the GMP231 depends on the interface you are using for adjustment.

Adjustment Types

You can adjust the CO₂ measurement of the GMP231 in one or two points.

- One-point adjustment is recommended if you are interested in maintaining a fixed CO₂ level inside the chamber. For best result, use a calibration gas with a CO₂ concentration that is close to the intended level.
- Two-point adjustment is recommended if you typically measure a variable CO₂ level.

Available adjustment functions depend on the interface you use to operate the GMP231. If you want to integrate the functionality into the incubator's control system, the I²C interface and the Vaisala industrial protocol are recommended. If you want to compare the reading of the GMP231 to a reference instrument as adjust it accordingly, use an MI70 hand-held indicator and a reference probe.

I²C Interface

I²C interface supports one and two-point adjustment sequences as well as configuration of the environmental compensation settings using the Get_Parameter and Set_Parameter commands. See the following sections:

- Adjust on page 65
- Get_Parameter on page 60
- Set_Parameter on page 62

Vaisala Industrial Protocol

Vaisala industrial protocol supports one and two-point adjustment with the CCO2 command. You can also adjust the internal pressure and temperature measurements with a simple offset correction. Configuration of the environmental compensation settings can be done using serial line commands. See the following sections:

- Calibration Commands on page 41
- Changing Measurement Settings on page 35

MI70 Hand-Held Indicator

MI70 hand-held indicator supports one-point adjustment, either using a calibration gas or using a reference instrument that is connected to the MI70. See section Calibration and Adjustment with MI70 Indicator on page 80.

CHAPTER 7

OPERATING WITH MI70 INDICATOR

Overview of MI70 Support

GMP231 is compatible with instruments that utilize the MI70 Indicator, for example the GM70 Hand-Held Carbon Dioxide Meter. The MI70 indicator is a convenient service tool for viewing the measurement readings, adjusting the environmental compensation settings, and performing calibration and one-point adjustment.




Figure 21 CO₂ Reading on MI70 Screen


Connecting GMP231 to MI70 Indicator

1. If the GMP231 is installed in an incubator, disconnect the incubator's cable from the 8-pin M12 connector. Note that GMP231 can remain physically connected to the incubator.
2. If the MI70 indicator is on, turn it off.
3. Connect the GMP231 to the MI70 indicator using the GMP231 service cable for MI70. See section Spare Parts and Accessories on page 88.
4. Turn on the MI70 indicator. MI70 detects the probe and proceeds to show the measurement screen. The parameters measured by GMP231 will start to show valid measurement results after a few seconds.

Changing Environmental Compensation Settings with MI70 Indicator

You can see the compensation values that are currently used by the GMP231 by selecting them as display quantities from **Main menu > Display > Quantities and Units**. The quantities are as follows:


- **Tcomp**: currently active temperature compensation value.
- **Pcomp**: currently active pressure compensation value.
- **Ocomp**: currently active oxygen concentration compensation value.
- **Hcomp**: currently active relative humidity compensation value.



1403-143

Figure 22 CO₂ Reading with Tcomp and Pcomp on MI70 Screen

You can change the compensation settings from **Main menu > Settings > Measurement settings**. For more information about the possible settings and their meaning, see Environmental Compensation on page 17.



1403-137

Figure 23 GMP231 Compensation Settings on MI70 Screen

NOTE

When you turn a compensation off, GMP231 still shows a value for the corresponding display quantity (for example, Pcomp shows 1013.2 hPa). This is the default compensation value that is mathematically neutral for the probe's internal compensation model.

Calibration and Adjustment with MI70 Indicator

NOTE

Before using the MI70 indicator for calibration and adjustment, read the instructions in section Calibration and Adjustment on page 74.

Make sure that the environmental compensation settings of the GMP231 are properly set for your calibration environment; see section Changing Environmental Compensation Settings with MI70 Indicator on page 79.

NOTE

When two probes are connected to the MI70 indicator, it uses Roman numerals “I” and “II” to indicate which port the parameter or function in question is connected to.

1-Point Adjustment with an MI70-Compatible Reference Probe

1. Connect the GMP231 to Port I of the MI70 indicator.
2. Connect the calibrated reference probe to Port II. Make sure the reference probe is in the same environment as the GMP231's sensor.
3. If you are using the calibration adapter to feed a calibration gas to the GMP231, you must feed the same gas to the reference probe also. Refer to the documentation of your reference probe on how to do this, and what accessories you need.
4. Turn on the MI70 indicator.
5. Start the adjustment sequence from **Main menu > Functions > Adjustments**.



1403-131


Figure 24 Functions Menu

6. MI70 notifies you that automatic power off is disabled during adjustment mode, press **OK** to acknowledge.

7. To proceed with the adjustment, select the **CO₂(I)** parameter in the **Select Quantity** screen.

In the **Select Quantity** screen you can also view the currently used compensation values, and the **Last adjustment date** information. You can update the date and text using the **CDATE** and **CTEXT** commands on the serial line.


8. You may be prompted to check the environmental settings of the reference probe before proceeding. Press **Yes** to check the settings and **Exit** when you have checked and corrected the settings.
9. The adjustment mode is now active, and you can see the measured CO₂ readings and their difference on the screen. Allow the measurement to stabilize. To proceed with the adjustment, press **Adjust**.



1403-134

Figure 25 Comparing Readings in MI70 Adjustment Mode

10. Select **To same as CO₂(II)**.



1403-142

Figure 26 Selecting the Adjustment Mode

11. You will be prompted if you really want to adjust. Select **Yes**.
12. If the adjustment is successful, the MI70 will show the text **Adjustment Done**, after which you will return to the adjustment mode. At this point you can press **Back** and **Exit** to leave the adjustment mode. The adjustment is now completed.

If the adjustment cannot be applied, the MI70 will show the text **Cannot adjust**, possibly followed by a text stating the reason. A possible reason for an adjustment failure is attempting to apply a very large correction to the reading. See section **Limits of Adjustment** on page 76.

1-Point Adjustment with a Reference Gas


1. Connect the GMP231 to Port I of the MI70 indicator.
2. Feed a calibration gas to the GMP231 using the calibration adapter accessory. If you are using ambient air as the calibration gas, you must have a reference meter in the same environment to verify the CO₂ concentration.
3. Turn on the MI70 indicator.
4. Start the adjustment sequence from **Main menu > Functions > Adjustments**.



1403-131

Figure 27 Functions Menu

5. MI70 notifies you that automatic power off is disabled during adjustment mode, press **OK** to acknowledge.
6. Select the CO₂ parameter when prompted.
7. You may be prompted to check the environmental settings of the reference probe before proceeding. Press **Yes** to check the settings and **Exit** when you have checked and corrected the settings.
8. The adjustment mode is now active, and you can see the measured CO₂ reading on the screen. To proceed with the adjustment, press **Adjust**.



1403-132

Figure 28 MI70 Adjustment Mode

9. Select **1-point adjustment**.




Figure 29 Selecting the Adjustment Mode

10. You will be prompted if you really want to adjust. Select **Yes**.
11. You are now in the 1-point adjustment screen. Allow the measurement to stabilize and press **Ready**.
12. Enter the CO₂ concentration of the reference gas and press **OK**.




Figure 30 Entering the Reference CO₂ Concentration

13. You will be prompted if you really want to adjust. Select **Yes**.
14. If the adjustment is successful, the MI70 will show the text **Adjustment Done**, after which you will return to the adjustment mode. At this point you can press **Back** and **Exit** to leave the adjustment mode. The adjustment is now completed.

If the adjustment cannot be applied, the MI70 will show the text **Cannot adjust**, possibly followed by a text stating the reason. A possible reason for an adjustment failure is attempting to apply a very large correction to the reading. See section Limits of Adjustment on page 76.

CHAPTER 8

TROUBLESHOOTING

This chapter describes possible problems, their probable causes and remedies, and provides contact information for technical support.

Problem Situations

Table 41 Possible Problem Situations and Their Remedies

Problem	Possible Cause	Remedy
Analog output reading is unchanging and appears incorrect.	Analog output is in error state. See section Analog Output Error State on page 85	Remove the cause of the error state and the analog output will recover its normal function.
Probe outputs stars "*****" on serial line instead of measurement data.	Incorrect supply voltage.	Check the power supply. Check the active errors using the ERRS command on the serial line.
	Unsuitable operating environment.	Verify that the operating environment is within specified operating limits.
Unable to access probe on the RS-485 line.	Incorrect wiring.	Check that the RS-485 connection is wired according to section Wiring on page 24. Power cycle or reset the probe and try again.
	Probe in POLL mode with unknown address.	Issue the ?? command to make the probe output its information. The use the OPEN command to open a line to the probe's address.
CO2 measurement not working.	Condensation on the sensor.	Remove the PTFE filter and check if condensation has formed on the sensor. If yes, dry out the condensation with instrument air and insert a new dry filter. Keep the probe powered and operating to prevent re-occurrence.

Analog Output Error State

GMP231 sets the analog output channel into a defined error level instead of the measured result in two situations:

- Probe detects a measurement malfunction. This means an actual measurement problem, such as sensor damage or unsuitable environmental conditions.
- Measured value(s) are well outside the scaled output range. For a more detailed explanation, see section Analog Output Overrange Behavior on page 19.

The default error level depends on the output type:

- For 4 ... 20 mA output, the default error level is **3.6 mA**
- For 0 ... 20 mA output, the default error level is **23 mA**.

The probe resumes normal operation of the analog output when the cause of the error state is removed.

Technical Support

For technical questions, Provide at least the following supporting information:

- Name and model of the product in question
- Serial number of the product
- Name and location of the installation site
- Name and contact information of a technically competent person who can provide further information on the problem.

Product Returns

WARNING

When returning a product for calibration or repair, make sure it has not been exposed to dangerous contamination, and is safe to handle without special precautions.

CHAPTER 9

TECHNICAL DATA

This chapter provides the technical data of the GMP231.

Specifications

Table 42 Performance

Property	Description / Value
Measurement range	0 ... 20 %CO ₂
Accuracy at 37 °C, 1013 hPa	
Repeatability at 0 ... 8 %CO ₂	±0.1 %CO ₂
Repeatability at 8 ... 12 %CO ₂	±0.2 %CO ₂
Repeatability at 12 ... 20 %CO ₂	±0.4 %CO ₂
Non-linearity at 0 ... 20 %CO ₂	±0.1 %CO ₂
Calibration uncertainty at 5 %CO ₂	±0.1 %CO ₂
Temperature dependence with compensation at	
3 ... 12 %CO ₂ , 20 ... 60 °C	±0.1 %CO ₂
0 ... 16 %CO ₂ , 0 ... 70 °C	±(0.1 %CO ₂ + 0.05 % of reading / °C)
16 ... 20 %CO ₂ , 0 ... 70 °C without compensation (typical)	±1.5 %CO ₂ -0.4 % of reading / °C
Pressure dependence with compensation at	
3 ... 12 %CO ₂ , 700 ... 1100 hPa	±0.015 % of reading / hPa
0 ... 20 %CO ₂ , 500 ... 1100 hPa without compensation (typical)	±(10 ppm + 0.020 % of reading) / hPa +0.15 % of reading / hPa
Humidity dependence with compensation at	
0 ... 20 %CO ₂ , 0 ... 100 %RH	±0.9% of reading (37 °C)
without compensation (typical)	+0.05% of reading / %RH
O ₂ dependence with compensation at	
0 ... 20 %CO ₂ , 0...90 %O ₂	±0.6 % of reading
without compensation (typical)	-0.08 % of reading / %O ₂
Start-up time	10 s
Warm-up time for full spec.	1 min
Response time	
T63	< 30 s
T90	< 50 s
Long-term stability	
0 ... 8 %CO ₂	< ±0.2 %CO ₂ / year
8 % ... 12 %CO ₂	< ±0.5 %CO ₂ / year
12 % ... 20 %CO ₂	< ±1.0 %CO ₂ / year

Table 43 Operating Environment

Property	Description / Value
Operating temperature of CO ₂ measurement	0 ... 70 °C
Max. temperature durability in standby mode	up to +195 °C
Heat sterilization (+180 °C) durability	At least 120 cycles
Storage temperature	-40 ... +75 °C
Pressure	
Compensated	500 ... 1100 hPa
Operating	< 1500 hPa
Humidity	0 ... 100 %, non-condensing
Condensation prevention	Sensor head heating when power on
Chemical tolerance	DMSO IPA (70% Isopropyl Alcohol, 30% water) H ₂ O ₂ (2000 ppm), non-condensing Ethanol Acetic acid
Electromagnetic compatibility	EN61326-1, Generic environment

Table 44 Inputs and Outputs

Property	Description / Value
Operating voltage	
When digital output in use	11...30 VDC
When analog output in use	20...30 VDC
Digital outputs	I ² C 5 V RS-485 (2-wire with Vaisala Industrial Protocol)
Analog output	0 ... 20 mA (scalable) max. load 600 Ω
Power consumption	< 1 W (pulsed)

Table 45 Mechanics

Property	Description / Value
Materials	
Housing	Metal coated plastic ABS+PC
Inner tube	Aluminum
Probe tube	PPSU
Filter	PTFE
Housing classifications	
Sensor head	IP54
Electronics housing	IP20
Connector	M12 / 8 pin
Weight	
Probe with cable	200 g
Probe without cable	150 g
Dimensions	
Probe tube max. diameter	30.2 mm
Probe tube min. diameter	24.8 mm
Probe tube length	118.5 mm
Sensor filter diameter	19 mm
Sensor filter length	12 mm

Spare Parts and Accessories

Table 46 Spare Parts and Accessories for GMP231

Description	Order Code
M12 Connection Cable 0.9 m with open ends	DRW240977SP
M12 Connection Cable 0.6 m with Milli-Grid connector	ASM210903SP
Service cable for MI70	221801
USB PC connection cable	221040
PTFE filter	DRW240494SP
Silicone plug	DRW240015SP
Attachment bracket	DRW240247SP
Calibration adapter for GMP231	239523

www.bodhi-mt.com

上海博众测量技术有限公司

Bodhi (Shanghai) measurement technology Co.,Ltd.
NO.32,ShuPing Road, JiadingDistrict,ZIP201808,
Shanghai R.P.China

TEL: 0086 21 6630 8161/62/63

FAX: 0086 21 6630 8167

